

## New Voice Messages added to the Pathfinder® Software

Version 2.2.0.3 of the Pathfinder® Configuration Software is available today to download. This new version replaces the current version 2.2.0.2. The following new features have been added to the software:



### COVID-19 Related Voice Messages

Ten standard COVID-19 related voice messages have been added to broadcast alerts in your community during this pandemic. The following standard voice messages are available in English, Spanish, and French Canadian:

- This jurisdiction is currently under a "Stay At Home Order" under direction of the Governor. You are only permitted to leave home for essential services or activities. Avoid gatherings of 10 or more people. Please abide by all CDC Guidelines and recommendations
- Please support our health officials and first responders during this time by observing local, state, and national recommendations for public health
- Thank you to all of our citizens for heading our local, state, and national leader's recommendations during this national health crisis. We will win this war against COVID19 with everyone's assistance and responsible actions
- A shelter in place order is in effect. Only travel for essential needs and services
- All public beaches and parks are closed to the public for the health of our state and country until further notice
- No more than 10 people per gathering. Please disperse
- Please do your part to help save lives, maintain social distancing and follow all CDC Guidelines
- Shelter in place
- Remain indoor
- The shelter in place order has been revoked. Continue social distancing and observe all CDC, local, state, and national recommendations

### Updated Training Guide

Pathfinder Training Guide has been updated and is available to download in the "Help" section. New updates include information on the 17-button controller, updated screenshots of current software, and information on the diagnostics feature and setting current limits for relays.

### Bug Fix

Following issues have been fixed:

- Rear ILS SignalMaster fast deselecting itself
- Missing polarity settings corrupting a .json file
- Amplifier forgetting OBD settings

### 2 Channel Flasher Added

#### T I M I N G

Version 2.2.0.3 of the Pathfinder Configuration Software can be download today at:

<https://www.fedsig.com/software-downloads>.

*For more information, contact your local Federal Signal sales representative  
or visit our website at [www.fedsig.com](http://www.fedsig.com)*